





Oct.1.2018 Copyright 2018 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
 In case that the application demands a high level of reliability, such as automotive,
 please contact a company representative for further information.





2 CONFIGURATION OF TWO AND FOUR CONTACTS.



CONFIGURATION OF ONE CONTACT.



POLARIZATION MARKING



CODE No.	PART No.	CONTACT	A	B
CL680-1026-7-28	DF22R-1S-7.92C(28)	1	8.00	—
CL680-1027-0-28	DF22R-2S-7.92C(28)	2	15.50	7.92
CL680-1028-2-28	DF22R-3S-7.92C(28)	3	23.42	15.84
CL680-1029-5-28	DF22R-4S-7.92C(28)	4	31.34	23.76
CL680-1030-4-28	DF22R-5S-7.92C(28)	5	39.26	31.68

NOTE1:UL (FILE NO. E52653)
 C:UL (FILE NO. E52653)
 TUV (FILE NO. R9950703) APPROVED PRODUCT.
 2 TWO AND FOUR CONTACTS DIFFER IN THE POSITION OF A GUIDE KEY.
 3:100 CONNECTORS ARE IN ONE PACK



NO.	MATERIAL	FINISH . REMARKS	NO.	MATERIAL	FINISH . REMARKS
			1	Polyamide	BLACK, UL94V-0
UNITS mm		SCALE 2 : 1	COUNT 2	DESCRIPTION OF REVISIONS	
				DESIGNED TO. KUROMATSU	CHECKED TS. FUKUSHIMA
				DATE 18.03.07	
				DRAWING NO. EDC3-308611-01	
				PART NO. DF22R-*S-7.92C(28)	
				CODE NO. CL680-	




Oct.1.2018 Copyright 2018 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
In case that the application demands a high level of reliability, such as automotive,
please contact a company representative for further information.




Precautions

Notification for harness assembly

- 1) When inserting the crimping terminal to the crimping socket, please do not tilt the crimping terminal or twist the cable.
Insertion at tilted angles or twisting the cable may cause deformation of the crimping terminal or crimping socket.
- 2) After inserting the crimping terminal to the crimping socket, please make sure that the lance has been hooked with pulling the cable lightly.
When checking the hook, please avoid bending the cable for preventing terminal drop-off.



- 3) Bundle cables/Cable Cables
Recommend bundle and strip position of cables are 100 mm or more.
Bundling close to the connectors may cause terminal drop-off, breaking cables and unstable connection.



HRS	DRAWING NO.	EDC3-308611-01
	PART NO.	DF22R-*S-7.92C(28)
	CODE NO.	CL680-
		2/3

Oct.1.2018 Copyright 2018 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
 In case that the application demands a high level of reliability, such as automotive,
 please contact a company representative for further information.






Precautions

Notification for Insertion Extraction

- 1) Please insert(extract) the crimping socket straight to the mating connector.
 Insertion(extraction) at tilted angles applies load concentration to the connector end and may cause deformation (at connection area, socket and header case, etc). There is firing risk using this kind of deformed connector.



Insertion(Extraction)





- 2) When it is hard to extract, please lightly insert the connector beforehand and then pull it with releasing the lock.
 Forced extraction has a risk of connector breakage.

Notification of wiring



- 1) When using a thick cable, short cable length and bending close to the connector end, these load concentration may cause deformation.
 Please note that there is firing risk using deformed connector.
 When installing, please refrain from stress concentration such as cable bending close to the connector end or cable twisting.



- 2) When applying load to connector end, please use the retainer for reducing the stress affection on the connector.
 Retainer shall be installed after inserted crimping contact completely. It might be impossible to insert it when terminal installation is incompletd.

HRS	DRAWING NO.	EDC3-308611-01
	PART NO.	DF22R-*S-7.92C(28)
	CODE NO.	CL680-
		3/3