Global Change Notification (GCN)

Product Family	6.2 W/W TPA / 7.3 W/W TPA	10695715
		GCN Number
Series	35150	June 26, 2015
		Date Issued
Reason For Change	New, Modified, Or Replacement Tooling	
Change Description	The purpose of this letter is to inform you that copy mold for 351500290, 351500292, 351500293, 351500294, 351500296, 351500390, 351500392, 351500393, 351500394 and 351500396 will be implemented. This additional tooling is needed in order to keep up with current and future demands of this product. There will be no change in product form, fit, or function. Implementation Date may be changed due to customer demand and production situation.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	New Capacity	
Assessment Of Change (How Product Will Be Qualified & Validated)	No impact to fit, form or function as a result of this change. Test report can be supplied at your request and can be communicated through your local Molex Sales Representative.	
Internal Molex Qualification Date (Planned Date Information Available)	June 15, 2015	
Sample Availability Date (Changed Part)	June 15, 2015	
Date of Implementation	July 26, 2015	
Method of Identifying Change	Lot Information in the label	
Recommended Replacement Parts	Not Applicable	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com