

Global Change Notification (GCN)

Product Family MXP120 sealed 10663118


GCN Number

Series 34900 December 10, 2014

Date Issued

Reason For Change New, Modified, Or Replacement Tooling

Change Description To improve connector un-mating ergonomics, we are implementing a different latch design on our receptacle connectors . The change has been already implemented on the 1x4 and needs to be implemented on the 1x6 as they share the same assembly equipment. Change will be implemented on 1x2 and 1x3 as well to be consistent in performance and features across the family. This change has been reviewed and approved by the OEM and immediate implementation has been requested.



Part Numbers Affected Please refer to CustomerPartList.csv attached to e-mail message.

Reason For Short Notice Exception Special Request

Assessment Of Change (How Product Will Be Qualified & Validated) validation testing

Internal Molex Qualification Date (Planned Date Information Available) January 30, 2015

Sample Availability Date (Changed Part) January 30, 2015

Date of Implementation January 31, 2015

Method of Identifying Change New part numbers issued

Recommended Replacement Parts NA

Last Time Buy Date for Obsolete Parts January 30, 2015

Last Time Ship Date for Obsolete Parts January 30, 2015

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com