

**PRODUCT / PROCESS CHANGE NOTIFICATION (PCN)****PCN Number:** CC165202**Notification Subject:** CRB 16-1457 Final Notice: Qualification of ATP assembly site for AT88RF1354-ZU and AT88RF1354-ZU-T catalog part numbers (CPN) available in 36L VQFN package.**PCN Issue Date:** January 10, 2017**Change Category:** Manufacturing location**PCN Status:** Final Notification**Microchip/Atmel Parts Affected:** Please open the attachments included with this PCN labeled as PCN\_#\_Affected\_CPN.**Description of Change:** Note: for your convenience Microchip/Atmel includes identical files in two formats (.pdf and .xls)

Qualification of ATP assembly site for AT88RF1354-ZU and AT88RF1354-ZU-T catalog part numbers (CPN) available in 36L VQFN package.

**Pre Change:** ATK assembly site**Post Change:** ATP assembly site**Pre and Post Change Summary:**

Description	Pre Change	Post Change
Assembly Site	ATK	ATP
Wire material	Au	Au
Die Attach	CRM1085A	CRM1085A
Mold Compound	G700	G700
Lead frame material	C194	C194

**Impacts to Data Sheet:** None**Change Impact:** None**Reason for Change:** To improve manufacturability by qualifying ATP assembly site. ATK assembly site will no longer have manufacturing support to assemble AT88RF1354-ZU and AT88RF1354-ZU-T catalog part numbers (CPN) available in 36L VQFN package.

**Change Implementation Status:**

Completed

**Estimated First Ship Date:**

February 01, 2017

Note: Please be advised that after the estimated first ship date customers may receive pre and post change parts.

**Time Table Summary:**

	January 2017				February 2017				
Workweek	01	02	03	04	05	06	07	08	09
Qual Report Availability		X							
Final PCN Issue Date		X							
Estimated Implementation Date					X				

**Method to Identify Change:**

Country code on the marking

**Qualification Report:**

Please open the attachments included with this PCN labeled as PCN\_#\_Qual Report

**Data Sheet:**

None

**Revision History:**

January 10, 2017: Issued final notification

Please contact your local [Microchip](#) or [Atmel](#) Sales Office or Distributor with questions or concerns regarding this notification.