

Product Change Notification



Product Group: SFERNICE /Oct 20, 2006/PCN-SF / FL 046- 2005 Rev 0

TRIMMERS: TSM4 / TS63 / T63

DESCRIPTION OF CHANGE: Sealing becomes BLACK (was blue) due to raw material obsolescence.

CLASSIFICATION OF CHANGE: Form Fit Function (pictures attached)

REASON FOR CHANGE: Raw Material Obsolescence

EXPECTED INFLUENCE ON QUALITY/RELIABILITY/PERFORMANCE: No effect.

PRODUCT CATEGORY: Trimmers

PART NUMBERS/SERIES/FAMILIES AFFECTED: TSM4XX , TS63XXX, T63XXX, TS6XXX & T6XXX,

VISHAY BRAND(s): Vishay Sfernice

TIME SCHEDULE:

Last Time Buy Date: n/a application production D/C > 0701

Last Time Shipment Date : n/a

SAMPLE AVAILABILITY: Immediate

PRODUCT IDENTIFICATION: Date Code, color

QUALIFICATION DATA: Available on request

This PCN is considered approved, without further notification, unless we receive specific customer concerns before 31/12/06 or as specified by contract.


ISSUED BY: Frederic Lovera / Marketing Mgr. Frederic.lovera@vishay.com

For further information, please contact your regional Vishay office.

CONTACT INFORMATION:

See your standard customer service

T63 Before After



TSM4 Before After



TS63 Before After

