



Product Change Notification

Current Date: 11-Dec-2019

TE Connectivity

Product Change Notification: P-19-018306

PCN Date: 09-DEC-19

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AMP MCP2.8 CONTACT

Description of Changes

Dear customer, we hereby inform you about a new duplication production tool (11-1935189) in TE Suzhou plant for production , TE part number 1-968849-1 & 1-968851-1 & 1-968880-1,This die capability only cover Asia-Pacific market currently. EMEA customer do not need to change to China part only keep EMEA part

Other attachments:

[Explanation for new duplication production tool for AMP MCP2.8 CONTACT](#)

Reason for Changes:

Customer Request.Customer Request.customer request ,as a result of our continuous strive for capacity increase of our procuton, we hreby inform you upfront about a new tool 11-1935189, which are under construction in order to meet all specification requirements to cover increasing marked demand and which will run in addition to current one.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

10-MAR-2020

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

31-DEC-2020

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number (s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968849-1	NO		TYC1-968849-1				
1-968851-1	NO		TYC1-968851-1				
1-968880-1	NO		TYC1-968880-1	"1-0968880-1"			



Product Change Notification

Current Date: 11-Dec-2019

TE Connectivity

Product Change Notification: P-19-018306

PCN Date: 09-DEC-19

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AMP MCP2.8 CONTACT

Description of Changes

Dear customer, we hereby inform you about a new duplication production tool (11-1935189) in TE Suzhou plant for production , TE part number 1-968849-1 & 1-968851-1 & 1-968880-1,This die capability only cover Asia-Pacific market currently. EMEA customer do not need to change to China part only keep EMEA part

Other attachments:

[Explanation for new duplication production tool for AMP MCP2.8 CONTACT](#)

Reason for Changes:

Customer Request.Customer Request.customer request ,as a result of our continuous strive for capacity increase of our procuton, we hreby inform you upfront about a new tool 11-1935189, which are under construction in order to meet all specification requirements to cover increasing marked demand and which will run in addition to current one.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

10-MAR-2020

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

31-DEC-2020

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number (s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968849-1	NO		TYC1-968849-1				
1-968851-1	NO		TYC1-968851-1				
1-968880-1	NO		TYC1-968880-1	"1-0968880-1"			