

Global Change Notification (GCN)

Product Family 0.64 cavity plug 10704567


GCN Number

Series 34586 July 31, 2015

Date Issued

Reason For Change New, Modified, Or Replacement Tooling

Change Description This letter is being sent to announce that Molex is adding a new mold to make the Cavity Plugs 34586-0001. The parts from the new mold will be identical to the parts from the current mold.



Series image - Reference only

Part Numbers Affected Please refer to CustomerPartList.csv attached to e-mail message.

Reason For Short Notice Exception

Assessment Of Change (How Product Will Be Qualified & Validated) Product from the new mold will be qualified by Molex before it is released to production. PPAP will be available upon request

Internal Molex Qualification Date (Planned Date Information Available) August 21, 2015

Sample Availability Date (Changed Part) August 21, 2015

Date of Implementation September 01, 2015

Method of Identifying Change Product made after August 21, 2015 could be from the new mold.

Recommended Replacement Parts Not Applicable

Last Time Buy Date for Obsolete Parts

Last Time Ship Date for Obsolete Parts

| Contact | Name | E-mail | Phone Number |
|---|---|----------------------------|-----------------|
| Sales Engineer | Please refer to e-mail message for your local sales engineer. | | |
| Regional Coordinator (Japan and Korea) | Naomi Maruyama | Naomi.Maruyama@molex.co.jp | +81-46-265-2416 |
| Regional Coordinator (Asia- excluding Japan and Korea) | Allen Yu | Allen.Yu@molex.com | +886-2-66251751 |
| Regional Coordinator (Europe, Middle East, Africa) | Agnes Mburu | Agnes.Mburu@molex.com | +31-40-295-8271 |
| Regional Coordinator (Americas) | Maria Sullivan | Maria.Sullivan@molex.com | 1-727-322-4352 |

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com