

Product Discontinuation



PD_045_18

■ Last Order Date:	2018-09-15
■ Last Delivery Date:	2019-03-15

Reason: Product Portfolio rationalization

DISCONTINUED				NEW (REPLACEMENT)			
Sales name	SP number	OPN	Package	Sales name	SP number	OPN	Package
BA 885	SP000010151	BA885E6327HTSA1	SOT23	none			
BA 885	SP000010150	BA885E7631HTMA1	SOT23	none			
BAR 61	SP000010169	BAR61E6327HTSA1	SOT143-4-1	none			
BA 595	SP000010146	BA595E6327HTSA1	SOD323	none			
BA 595	SP000010149	BA595E6359HTMA1	SOD323	none			
BA 895-02 V	SP001179590	BA89502VH6327XTSA1	SC79	none			

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!